MEDICAL IMAGING

CSO Customer Support Operations

Technical Documentation

Order No.: DD+DIS197.00E

1 Piece T7ZDM MA1

ADC COMPACT

Type 5145 / 100/101/140

Type 5145 / 200/201/240

2nd Edition



printed in Germany

AGFA

AGFA-GEVAERT AG
MI - CSO / Information & Projects
Tegernseer Landstr. 161

D-81539 München

Bestellen von Ersatzteilen und Ersatzteilsortimenten: To order spare parts and spare part assortments: Commande de pièces détachées et assortiments des pièces détachées:	**Tel.: xx49 - (0)89 - 6207 - 3760** **Fax.: xx49 - (0)89 - 6207 - 7388**
Bestellen von Dokumentation: To order documentation: Commande de documentation:	**Tel.: xx49 - (0)89 - 6207 - 3553** **Fax.: xx49 - (0)89 - 6207 - 7271**

0. Order list

1. Preinstallation

2. Controls and Connections

3. Installation / Machine Start-up

4. Operating Instructions

5. Functional Description

6. Repair and Service

- 6.1 Safety regulations / general hints for repair work
- 6.2 Tools and auxiliary means (also software tools)
- 6.3 Troubleshooting
- 6.4 Electrical and mechanical codes, fuse tables
- 6.5 Replacement of parts, including adjustment instructions when applicable
- 6.6 Adjustments (software and hardware)

7. Reference and Circuit Diagrams

8. Spare Parts List

9. Accessories

10. Modifications

11. Technical Standard Modifications

12. Maintenance

13. Fieldservice Bulletins

14. Installation Planning

15. Glossary / Key Word Index

Caution:

This system uses high voltage. Please consider the respective safety regulations.

These instructions describe adjustments and routines which must only be performed by qualified technical personnel.

Note:

Electrical repairs and connections must only be performed by a qualified electrician.

Mechanical repairs and connections must only be performed by a qualified technician.